


Fig. 14G








Fig. 14H 28 16 .70 36 70 **7**5'-26 32 -12 -30





= Diamagnet

= Permanent Magnet

= Magnet Means

Fig. 14J 16 75--75 70' -70' 75[']-36-70 75'--12

-30

07/990,985

75

-70'

26

32


-12

-30

= Diamagnet

= Permanent Magnet

 \bigotimes = Magnet Means



75'-





Fig. 14L






Fig. 14M

